



Plate 1: Front elevation.



Plate 2: Rear carpark, overflow carpark in forefront.





Plate 3: Rear boundary fence.



Plate 4: Coping stone damage to right hand wall of carpark.





Plate 5: Heavy vegetation growth to right hand boundary.



Plate 6: Dwarf stone wall to front of carpark worn.





Plate 7: Uneven paving slabs to rear left corner of building.



Plate 8: Rear elevation, roof in good order.



Plate 9: Slight wear to timber eaves to rear.



Plate 10: Inadequately supported uPVC gutter to porch to left hand side.





Plate 11: Moss and water staining to RHS of building.



Plate 12: Wear to brickwork at low level to bottom left corner of fire door to rear.



Plate 13: Moss build up to roof at the front.



Plate 14: Skylight partly covered with grime.





Plate 15: Village hall.



Plate 16: Stage in hall.





Plate 17: Timber roof and acoustic panel ceiling.



Plate 18: Dining area next to kitchen showing high level of decoration common throughout building.



Plate 19: High grade floor covering in diner and lobby.